

PUFAS Universal Fixative PT41

PUFAS Universal Fixierung PT41

- for PVC and textile floor coverings with non-woven, latex and PVC foam backing
- easily removable
- suitable for chair castors toEN 12529
- suitable for floor heating systems
- for absorbent and non-absorbent substrates
- solvent-free

Instructions for use:

PUFAS Universal Fixative PT 41 is most useful for fixing PVC/CV floor coverings and carpets with jute, textile and foam backing. Gluing can take place on all surfaces in indoor areas such as floor tiles, cement screed, PVC floor coverings, floor-levelling compound, etc. Suitable for chair castor roller loads to DIN 68131. Can also be used for heated floor structures.

Technical specifications:

Components: synthetic resin dispersion, natural

resinderivates, filling material

Density: approx. 1.2 g/cm³ pH-value: approx. 5 - 6 Usage: 200-300 g/m³

Substrate preparation:

Surface must be dry, stable, humidity-resistant and free from parting compounds. Level cracks, holes and irregularities with AKAPLAN Floor levelling Pretreat strongly absorbent and sanding surfaces with PUFAS Deeply- Penetrating Primer LF – solvent free.

Parquet floor must have absolutely waterproof sealing.

Application:

Apply PUFAS Universal Fixative PT 41 evenly onto the surface using a roller or serrated trowel (A2 toothing). Insert the cut flooring into the glue bed and press on evenly. Prior to the laying work, the applied adhesive must have completely flashed off in the case of glueing PVC or CV floor coverings onto non-absorbent surfaces. The fixative should not form threads any longer and should feel slightly sticky. Weigh down edges and joints if necessary.

The laying instructions of the floor covering manufacturers must be complied with.

Remove adhesive residues immediately with water. Clean any working equipment with water immediately after use

Adhesive residues can be removed, in the case of later removal of the floor covering, by soaking them with water while adding PUFAS Wallpaper Re-mover (application time approx. 15 minutes). Afterwards, remove the de-tached fixation using a spatula and rinse the whole surface thoroughly with water

Note:

Please see EU safety data sheet for all safety-related data (EU-CLP)

Do not use if the surface and/or room temperature are below + 5° Celsius!

Clean tools in water after use.

Considerations disposal:

Please see EU safety data sheet section 13 (EWC).

Storage:

Store in a cool place! Keep container tightly closed!

Available sizes:

3 kg	4007954022023	002202000	REG
5 kg	4007954022030	002203000	REG
10 kg	4007954022047	002204000	REG